

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/10/9	MAKE	HITACHI	MODEL	ZX75US-3
SERIAL	HCM1P300K00061306		STAMP	HCM1P300K00061306	
HR METER	4425	HR	YEAR	YR	
CAB/CNP	ROPS CAB (CAB) ROPS CNP / CNP / NONE	SHOE	450G PADS		

ENGINE : MODEL 4LE2 S/N 254837

Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	<input checked="" type="radio"/> YES · NO	

MAIN PUMP

Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	

COOLING SYSTEM

Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	

OPERATING SYSTEM

Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	

INTERIOR See Photos. 写真参照

Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	

BOOM / ARM / BKT

Boom	<input checked="" type="radio"/> FAIR · Attn	ガタあり LOOSE
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn	
Arm	<input checked="" type="radio"/> FAIR · Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn	
BKT	<input checked="" type="radio"/> FAIR · Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

COMMENT

BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO

ARM-CRANE YES ·  NO

BLADE  YES · NO

OFFSET YES ·  NO

OFFSET Cylinder FAIR · Attn

Piping  YES · NO Breaker only  Multi

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。