

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/9/12	MAKE	HITACHI	MODEL	ZX20U
SERIAL	HCM1MY00L00010319		STAMP	HCM1MY00L00010319	
HR METER	1975	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	250G PADS	

ENGINE : MODEL		S/N
Oil leakage	<small>FAIR</small> · (Attn)	油汚れあり OIL STAINS
Blow-By	<small>FAIR</small> · (Attn)	A LITTLE · (MIDDLE) · SEVERE
Sound	<small>FAIR</small> · (Attn)	
Oil	<small>FAIR</small> · (Attn)	
Exhaust Color	<small>FAIR</small> · (Attn)	
US EPA	YES · (NO)	
MAIN PUMP		
Sound	<small>FAIR</small> · (Attn)	
Oil leakage	<small>FAIR</small> · (Attn)	
Power	<small>FAIR</small> · (Attn)	
COOLING SYSTEM		
Radiator	<small>FAIR</small> · (Attn)	
Oil Cooler	<small>FAIR</small> · (Attn)	
OPERATING SYSTEM		
Swing	<small>FAIR</small> · (Attn)	
Travel	<small>FAIR</small> · (Attn)	
INTERIOR See Photos. 写真参照		
Operator's Seat	<small>FAIR</small> · (Attn)	切れあり CUT
Inside Cover	<small>FAIR</small> · (Attn)	
Glasses	<small>FAIR</small> · (Attn)	
AirCon	A/C · H/C · H only · C only · (None)	
BOOM / ARM / BKT		
Boom	<small>FAIR</small> · (Attn)	
Boom Cylinder	<small>FAIR</small> · (Attn)	
Arm	<small>FAIR</small> · (Attn)	
Arm Cylinder	<small>FAIR</small> · (Attn)	
BKT	<small>FAIR</small> · (Attn)	
BKT Cylinder	<small>FAIR</small> · (Attn)	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER ()
Lever	(LONG) · WRIST
Multi	MULTI · 2 · (NO)
ARM-CRANE	YES · (NO)
BLADE	(YES) · NO
OFFSET	YES · (NO)
OFFSET Cylinder	FAIR · (Attn)
Piping	(YES) · NO Breaker only · (Multi)
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。