

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2024/10/21	MAKE	KOMATSU	MODEL	D65PX-17
SERIAL	2962		STAMP	KMT0D117HFA002962	
HR METER	4811	HR	SHOE	930LGP	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER		CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
<b>OPERATION PUMP</b>		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
<b>COOLING SYSTEM</b>		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
<b>TRANSMISSION &amp; TRAVEL</b>		
T/M TYPE	(PS) · DD	DIFF. STEERING (YES) · NO
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	(FAIR) · Attn	破れあり TORN
Inside Cover	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
<b>BLADE &amp; CYLINDERS</b>		
BLADE	(FAIR) · Attn	
CYLD.(R)	(FAIR) · Attn	
CYLD.(L)	(FAIR) · Attn	
TILT CYLD	(FAIR) · Attn	
ANGLE CYLD	FAIR · Attn	

<b>UNDERCARRIAGE See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
<b>COMMENT</b>			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	(FAIR) · Attn		
EQUALIZER BAR	(FAIR) · Attn		
<b>COMMENT</b>			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。