

INSPECTION SHEET 検品書  
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/8/26	MAKE	TCM	MODEL	L13-3
SERIAL	RYU4F000T00007752		STAMP	S50-07752	
HR METER	13529	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP		NONE	TIRE SIZE	16.9-24 10PR

ENGINE : MODEL	S/N
Oil leakage	FAIR · <input checked="" type="radio"/> Attn *1
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · <input checked="" type="radio"/> NO
<b>OPERATION PUMP</b>	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
<b>COOLING SYSTEM</b>	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
<b>TRANSMISSION &amp; TRAVEL</b>	
T/M TYPE	<input checked="" type="radio"/> PS · DD
Transmission	FAIR · Attn
Travel	FAIR · Attn
FOOT BRAKE	FAIR · Attn
PARKING BRAKE	FAIR · <input checked="" type="radio"/> Attn *2
<b>INTERIOR See Photos. 写真参照</b>	
Operator's Seat	FAIR · <input checked="" type="radio"/> Attn 破れあり CUTS
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None
<b>FRONT &amp; CYLINDERS</b>	
Arm	FAIR · Attn
Bell crank	FAIR · Attn
Bucket	FAIR · <input checked="" type="radio"/> Attn 穴あり HOLES
Articulate	FAIR · Attn

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b>	
STEERING TYPE <input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING	
RIDE CONTROL	YES · <input checked="" type="radio"/> NO
<b>ATTACHMENTS</b>	
STD BKT	<input checked="" type="radio"/> YES · OTHER
BLADE	YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO
<b>COMMENT</b>	
*1 タービン周り油漏れ小 AROUND TURBIN: OIL LEAKING	
*2 パーキングランプ故障あり PARKING LAMP: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。