

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/10/18	MAKE	HITACHI	MODEL	ZX120-3
SERIAL	HCM1R100A00086923		STAMP	HCM1R100A00086923	
HR METER	5085	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	500G		

**ENGINE : MODEL** 4JJ1 **S/N** 134329

Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	<input checked="" type="radio"/> YES · NO	

**MAIN PUMP**

Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	

**COOLING SYSTEM**

Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	

**OPERATING SYSTEM**

Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	

**INTERIOR See Photos. 写真参照**

Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れあり CUTS
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	

**BOOM / ARM / BKT**

Boom	<input checked="" type="radio"/> FAIR · Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn	
Arm	<input checked="" type="radio"/> FAIR · Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn	
BKT	<input checked="" type="radio"/> FAIR · Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn	

**UNDERCARRIAGE : See Photos. 写真参照**

**RUST** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

**COMMENT**

.....  
.....  
.....  
.....

**BKT**  STD / SLOPE / NARROW / SKELETON / OTHER ( )

**Lever** LONG ·  WRIST

**Multi**  MULTI · 2 · NO

**ARM-CRANE** YES ·  NO

**BLADE** YES ·  NO

**OFFSET** YES ·  NO

**OFFSET Cylinder** FAIR · Attn

**Piping**  YES · NO Breaker only  Multi

**COMMENT**

.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....  
.....

**RUST of BODY** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。