

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

|                 |   |      |        |       |         |
|-----------------|---|------|--------|-------|---------|
| INSPECTION DATE | 2024/9/20                                     | MAKE | KUBOTA | MODEL | U-20-3S |
| SERIAL          | 15083   |      | STAMP  | 15083 |         |
| HR METER        | 3214  | HR   | YEAR   | YR    |         |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / <b>CNP</b> / NONE |      | SHOE   | 250R  |         |

|                                  |   |                            |
|----------------------------------|---|----------------------------|
| <b>ENGINE : MODEL</b>            | <b>S/N</b>  | 1DC7887                    |
| Oil leakage                      | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Blow-By                          | <input checked="" type="radio"/> FAIR · Attn                        | A LITTLE · MIDDLE · SEVERE |
| Sound                            | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Oil                              | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Exhaust Color                    | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| US EPA                           | YES · <input checked="" type="radio"/> NO                           |                            |
| <b>MAIN PUMP</b>                 |   |                            |
| Sound                            | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Oil leakage                      | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Power                            | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| <b>COOLING SYSTEM</b>            |   |                            |
| Radiator                         | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Oil Cooler                       | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| <b>OPERATING SYSTEM</b>          |   |                            |
| Swing                            | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Travel                           | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| <b>INTERIOR See Photos. 写真参照</b> |   |                            |
| Operator's Seat                  | FAIR · <input checked="" type="radio"/> Attn                        | 破れあり CUTS                  |
| Inside Cover                     | FAIR · Attn   |                            |
| Glasses                          | FAIR · Attn   |                            |
| AirCon                           | A/C · H/C · H only · C only · <input checked="" type="radio"/> None |                            |
| <b>BOOM / ARM / BKT</b>          |   |                            |
| Boom                             | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Boom Cylinder                    | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Arm                              | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Arm Cylinder                     | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| BKT                              | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| BKT Cylinder                     | <input checked="" type="radio"/> FAIR · Attn                        |                            |

|  |   |
|--|---|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |   |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | <b>3</b>  |
| <b>COMMENT</b>   |   |
|  |   |
|  |   |
| BKT  | <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ( )                    |
| Lever  | LONG · <input checked="" type="radio"/> WRIST   |
| Multi  | MULTI · 2 · <input checked="" type="radio"/> NO   |
| ARM-CRANE  | YES · <input checked="" type="radio"/> NO   |
| BLADE  | <input checked="" type="radio"/> YES · NO   |
| OFFSET   | YES · <input checked="" type="radio"/> NO   |
| OFFSET Cylinder  | FAIR · Attn   |
| Piping   | <input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi |
| <b>COMMENT</b>   |   |
|  |   |
|  |   |
|  |   |
|  |   |
|  |   |
|  |   |
|  |   |
|  |   |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | <b>3</b>  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。