

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/9/13	MAKE	CAT	MODEL	314DCR
SERIAL	CAT0314DCMFK00229		STAMP	CAT0314DCMFK00229	
HR METER	UNKNOWN / 8710	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	500G PADS		

ENGINE : MODEL	C4.2	S/N	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	<input checked="" type="radio"/> YES	NO	
MAIN PUMP			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	
OPERATING SYSTEM			
Swing	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	
INTERIOR See Photos. 写真参照			
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	
Inside Cover	<input checked="" type="radio"/> FAIR	Attn	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	H/C · H only · C only · None	
BOOM / ARM / BKT			
Boom	<input checked="" type="radio"/> FAIR	Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn	
Arm	<input checked="" type="radio"/> FAIR	Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn	
BKT	<input checked="" type="radio"/> FAIR	Attn	裏摩耗あり WORN
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO *1
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi
COMMENT	
本体側HRメーター故障あり ONE OF HR METERS: MALFUNCTION	
A/C故障あり A/C: MALFUNCTION	
*1 クレーンモード時アラーム作動、アーム動かない	
*1 WARNING SOUNDS & BEING UNABLE TO OPERATE THE ARM ON CRANE MODE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。