

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/9/20	MAKE	CAT	MODEL	320ERR-2
SERIAL	CAT0320ELLHN00655		STAMP	CAT0320ELLHN00655	
HR METER	20076 / 20072	HR	YEAR	YR	
CAB/CNP	<input checked="" type="radio"/> ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE		700G	

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
MAIN PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · <input checked="" type="radio"/> Attn	破れあり MUCH WORN
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	<input checked="" type="radio"/> FAIR · Attn	
Boom Cylinder	FAIR · <input checked="" type="radio"/> Attn	*1
Arm	<input checked="" type="radio"/> FAIR · Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn	
BKT	FAIR · <input checked="" type="radio"/> Attn	裏摩耗あり WORN
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
足周り石灰付着あり LIME STAINS	
BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="" type="radio"/> NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi
COMMENT	
*1 左シリンダー油漏れ小 LEFT CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。