

**INSPECTION SHEET 検品書  
EXCAVATOR バックホー**

INSPECTION DATE	2024/9/24	MAKE	YANMAR	MODEL	VIO15
SERIAL	NO PLATE		STAMP	10539B	
HR METER	3828	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	230R	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR <input checked="" type="radio"/> Attn *1	
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	
US EPA	YES <input type="radio"/> <u>NO</u>	
<b>MAIN PUMP</b>		
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	
Power	FAIR <input checked="" type="radio"/> Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	
<b>OPERATING SYSTEM</b>		
Swing	FAIR <input checked="" type="radio"/> Attn	
Travel	FAIR <input checked="" type="radio"/> Attn	
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	破れあり CUTS
Inside Cover	FAIR <input type="radio"/> Attn	
Glasses	FAIR <input type="radio"/> Attn	
AirCon	A/C · H/C · H only · C only · <u>None</u>	
<b>BOOM / ARM / BKT</b>		
Boom	FAIR <input checked="" type="radio"/> Attn	ガタあり LOOSE
Boom Cylinder	FAIR <input checked="" type="radio"/> Attn	
Arm	FAIR <input checked="" type="radio"/> Attn	ガタあり LOOSE
Arm Cylinder	FAIR <input checked="" type="radio"/> Attn	
BKT	FAIR <input checked="" type="radio"/> Attn	ガタあり LOOSE
BKT Cylinder	FAIR <input checked="" type="radio"/> Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	<u>LONG</u> · WRIST
Multi	MULTI · 2 · <u>NO</u>
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
<b>COMMENT</b>	
チャージランプ点灯あり CHARGE LAMP: ON	
*1 ヘッドカバー周り油漏れ小 AROUND HEAD COVER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。