

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/2/28	MAKE	HITACHI	MODEL	ZX75US-3
SERIAL	HCM1P300H00060987			STAMP	HCM1P300H00060987
HR METER	8816	HR	YEAR	2010	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	450G PADS

ENGINE : MODEL 4LE2 S/N	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn 油漏れ小 OIL LEAKING
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
OPERATING SYSTEM	
Swing	FAIR · Attn ガタあり SWING: LOOSE
Travel	FAIR · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	FAIR · Attn
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn *1
AirCon	A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	FAIR · Attn
Boom Cylinder	FAIR · Attn
Arm	FAIR · Attn ガタあり LOOSE
Arm Cylinder	FAIR · Attn 油漏れ小 OIL LEAKING
BKT	FAIR · Attn
BKT Cylinder	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi 5
COMMENT	
コントロールバルブ配管周りにじみあり	
AROUND SOME PIPE OF CONTROL VALVE: OIL OOZING	
バッテリーチャージ警告表示あり WARNING DISPLAY FOR CHARGING	
*1 F下部ガラス: ポリカーボネート	
*1 LOWER WINDSHIELD: POLYCARBONATE BOARD	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。