INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTION	2024/10/3				MAKE M		IOROOKA		MODEL		MST-800VD			
SERIAL	4459				9			STAMP				4459		
HR METER	2429 HR			Odometer				ŀ	km `	YEAR			YR	
CAB/CNP	ROPS CA	AB (C	CAB /	ROP	S CNF	P / CNP	/ NONE	SHOE		600F	₹	TIRE		
ENGINE :	N		MAIN FRAME											
Oil leakage	FAIR · Attn							MAIN FL/	AME	FAIR	■ Attn			
Blow-By	FAIR · Attn	A LITT	rle •	MIDDL	E•	SEVERE		VESSEL			<u> </u>			
Sound	FAIR · Attn							VESSE	L	FAIR	 Attn 			
Oil	FAIR · Attn							REAR GATE	TYPK	\z	ORMAL	L-	-GATE (FLAT)	
Exhaust Color	FAIR · Attn							REAR GA	ATE	FAIR	Attn			
US EPA	YES) · NO						UNDERCARRIAGE: See Photos. 写真参照							
OPERATION PUMP								RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3						
Sound	FAIR · Attn							COMMENT	-					
Oil leakage	FAIR · Attn							バッテリーカバ	ーヒンシ	ジ破損な	あり SOM	IE BATTER	Y COVER HINGE:	BROKEN
Power	FAIR · Attn													
COOLING	SYSTEM													
Radiator	FAIR · Attn													
Oil Cooler	FAIR · Attn													
TRANSMIS	TRANSMISSION & TRAVEL													
T/M TYPE	PS) · DD				No. OF	GEARS 2	GEARS							
Transmission	FAIR · Attn					•								
Travel	FAIR · Attn													
Swing	FAIR · Attn													
Articulate	FAIR · Attn													
FOOT BRAKE	FAIR · Attn													
PARKING BRAKE	FAIR · Attn													
INTERIOR See Photos. 写真参照														
Operator's Seat	FAIR · Attn	破れあ	jり T	ORN										
Inside Cover	FAIR · Attn													
Glasses	FAIR · Attn													
AirCon	A/C •	H/C	• (d only	• 0	only •	None	RUST of BODY	(5: NONE	, 4: A Li	ITTLE, 3: M	IIDDLE, 2: MU	CH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。