INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2024/9/17	MAKE	BOMAG	MODEL	BW115AC
SERIAL	222570	STAMP	NOT FOUND		
HR METER	4214 HR	Odometer	– km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE	9.5/65-15 6PR		

ENGINE : MODEL S/N		
Oil leakage	FAIR ・Attn	*1
Blow-By	FAIR・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	FAIR・ Attn	
Oil	FAIR・ Attn	
Exhaust Color	FAIR ・Attn	青煙あり BLUE FUMES
US EPA	YES ・NO	
OPERATION PUMP		
Sound	FAIR・ Attn	
Oil leakage	FAIR・ Attn	
Power	FAIR・ Attn	
COOLING SYSTEM		
Radiator	FAIR・ Attn	
Oil Cooler	FAIR・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS・ DD	
Transmission	FAIR・ Attn	
Travel	FAIR・ Attn	
FOOT BRAKE	FAIR・ Attn	
PARKING BRAKE	FAIR・ Attn	
INTERIOR	See Photos. 写真参照	
Operator's Seat	FAIR ・Attn	破れあり CUTS
Inside Cover	FAIR ・ Attn	
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・ None	
OTHERS		
Vibratory	FAIR・ Attn	
Watering	FAIR・ Attn	
Articulate	FAIR・ Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

COMMENT

*1 ヘッドカバー周り油漏れ小 AROUND HEAD COVER: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。