

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/23	MAKE	KOBELCO	MODEL	SK125SR
SERIAL	YV05-05054		STAMP	YV05-05054	
HR METER	4890	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL		D04FR	S/N	002981
Oil leakage	<input checked="" type="radio"/> FAIR	Attn		
Blow-By	<input checked="" type="radio"/> FAIR	Attn A LITTLE · MIDDLE · SEVERE		
Sound	<input checked="" type="radio"/> FAIR	Attn		
Oil	<input checked="" type="radio"/> FAIR	Attn		
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn		
US EPA	<input checked="" type="radio"/> YES	NO		
MAIN PUMP				
Sound	<input checked="" type="radio"/> FAIR	Attn		
Oil leakage	<input checked="" type="radio"/> FAIR	Attn		
Power	<input checked="" type="radio"/> FAIR	Attn		
COOLING SYSTEM				
Radiator	<input checked="" type="radio"/> FAIR	Attn		
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn		
OPERATING SYSTEM				
Swing	<input checked="" type="radio"/> FAIR	Attn		
Travel	<input checked="" type="radio"/> FAIR	Attn		
INTERIOR See Photos. 写真参照				
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn 破れあり CUTS		
Inside Cover	<input checked="" type="radio"/> FAIR	Attn		
Glasses	<input checked="" type="radio"/> FAIR	Attn		
AirCon	<input checked="" type="radio"/> A/C	H/C · H only · C only · None		
BOOM / ARM / BKT				
Boom	<input checked="" type="radio"/> FAIR	Attn		
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn		
Arm	<input checked="" type="radio"/> FAIR	Attn		
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn		
BKT	<input checked="" type="radio"/> FAIR	Attn		
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。