

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/18	MAKE	KUBOTA	MODEL	U-15-3S
SERIAL	41861		STAMP	41861	
HR METER	2294	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <input checked="" type="radio"/> CNP / NONE		SHOE	230R	

ENGINE : MODEL S/N	UNDERCARRIAGE : See Photos. 写真参照
Oil leakage <input checked="" type="radio"/> FAIR · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2
Blow-By <input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE	COMMENT
Sound <input checked="" type="radio"/> FAIR · Attn	可変脚仕様 VARIABLE WIDTH UNDERCARRIAGE
Oil <input checked="" type="radio"/> FAIR · Attn	
Exhaust Color <input checked="" type="radio"/> FAIR · Attn	
US EPA YES · <input checked="" type="radio"/> NO	
MAIN PUMP	BKT <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Sound <input checked="" type="radio"/> FAIR · Attn	Lever LONG · <input checked="" type="radio"/> WRIST
Oil leakage <input checked="" type="radio"/> FAIR · Attn	Multi <input checked="" type="radio"/> MULTI · 2 · NO
Power <input checked="" type="radio"/> FAIR · Attn	ARM-CRANE YES · <input checked="" type="radio"/> NO
COOLING SYSTEM	BLADE <input checked="" type="radio"/> YES · NO
Radiator <input checked="" type="radio"/> FAIR · Attn	OFFSET YES · <input checked="" type="radio"/> NO
Oil Cooler <input checked="" type="radio"/> FAIR · Attn	OFFSET Cylinder FAIR · Attn
OPERATING SYSTEM	Piping YES · <input checked="" type="radio"/> NO Breaker only · Multi
Swing <input checked="" type="radio"/> FAIR · Attn	COMMENT
Travel <input checked="" type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照	
Operator's Seat FAIR · <input checked="" type="radio"/> Attn 破れあり CUTS	
Inside Cover FAIR · Attn	
Glasses FAIR · Attn	
AirCon A/C · H/C · H only · C only · <input checked="" type="radio"/> None	
BOOM / ARM / BKT	
Boom <input checked="" type="radio"/> FAIR · Attn	
Boom Cylinder <input checked="" type="radio"/> FAIR · Attn	
Arm <input checked="" type="radio"/> FAIR · Attn	
Arm Cylinder <input checked="" type="radio"/> FAIR · Attn	
BKT <input checked="" type="radio"/> FAIR · Attn	
BKT Cylinder <input checked="" type="radio"/> FAIR · Attn	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。