# INSPECTION SHEET 検品書
## EXCAVATOR バックホー

| | | | | | |
|---|---|---|---|---|---|
| INSPECTION DATE | 2024/10/18 | MAKE | KUBOTA | MODEL | U-10-3 |
| SERIAL | 30525 | | | STAMP | 30525 |
| HR METER | 453 HR | | | YEAR | YR |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / CNP / NONE | | | SHOE | 230R |

| ENGINE : MODEL | S/N 4HW5321 | |
|---|---|---|
| Oil leakage | FAIR・Attn | |
| Blow-By | FAIR・Attn | A LITTLE・MIDDLE・SEVERE |
| Sound | FAIR・Attn | |
| Oil | FAIR・Attn | |
| Exhaust Color | FAIR・Attn | |
| US EPA | YES・NO | |
| **MAIN PUMP** | | |
| Sound | FAIR・Attn | |
| Oil leakage | FAIR・Attn | |
| Power | FAIR・Attn | |
| **COOLING SYSTEM** | | |
| Radiator | FAIR・Attn | |
| Oil Cooler | FAIR・Attn | |
| **OPERATING SYSTEM** | | |
| Swing | FAIR・Attn | |
| Travel | FAIR・Attn | |
| **INTERIOR** | See Photos. 写真参照 | |
| Operator's Seat | FAIR・Attn | |
| Inside Cover | FAIR・Attn | |
| Glasses | FAIR・Attn | |
| AirCon | A/C・H/C・H only・C only・None | |
| **BOOM / ARM / BKT** | | |
| Boom | FAIR・Attn | |
| Boom Cylinder | FAIR・Attn | |
| Arm | FAIR・Attn | |
| Arm Cylinder | FAIR・Attn | |
| BKT | FAIR・Attn | |
| BKT Cylinder | FAIR・Attn | |

| UNDERCARRIAGE : See Photos. 写真参照 | | |
|---|---|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | 3 |
| COMMENT | | |
| 可変脚仕様 VARIABLE WIDTH UNDERCARRIAGE | | |
| BKT | STD / SLOPE / NARROW / SKELETON / OTHER( ) | |
| Lever | LONG・WRIST | |
| Multi | MULTI・2・NO | |
| ARM-CRANE | YES・NO | |
| BLADE | YES・NO | |
| OFFSET | YES・NO | |
| OFFSET Cylinder | FAIR・Attn | |
| Piping | YES・NO | Breaker only・Multi |
| COMMENT | | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | 4 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。