INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/18	MAKE	KOMATSU	MODEL	PC55MR-5
SERIAL	21380			STAMP	KMTPC259JJE021380
HR METER	1534 HR			YEAR	YR
CAB/CNP	ROPS CAB / CAB / (ROPS CNP) / CNP / NONE			SHOE	400R

ENGINE : MODEL	S/N	
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	(YES) · NO	
MAIN PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
INTERIOR	**See Photos. 写真参照**	
Operator's Seat	(FAIR) · Attn	
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
BOOM / ARM / BKT		
Boom	(FAIR) · Attn	
Boom Cylinder	(FAIR) · Attn	
Arm	(FAIR) · Attn	
Arm Cylinder	(FAIR) · Attn	
BKT	(FAIR) · Attn	
BKT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
COMMENT		
BKT	STD / (SLOPE) / NARROW / SKELETON / OTHER( )	
Lever	LONG · (WRIST)	
Multi	MULTI · 2 · (NO)	
ARM-CRANE	(YES) · NO	
BLADE	(YES) · NO	
OFFSET	YES · (NO)	
OFFSET Cylinder	FAIR · Attn	
Piping	YES · (NO)	Breaker only · Multi
COMMENT		
付属品:STDバケット STANDARD BUCKET AS SPARE		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。