

INSPECTION SHEET 検品書
CARRY DUMP キャリーダンプ

INSPECTION DATE	2024/10/18	MAKE	MOROOKA	MODEL	MST-2300		
SERIAL	233152		STAMP	233152			
HR METER	4942	HR	Odometer	km	YEAR	1997	YR
CAB/CNP	ROPS CAB / CAB /	ROPS CNP / CNP /	NONE	SHOE	750R	TIRE	

ENGINE : MODEL		S/N	MAIN FRAME	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		MAIN FLAME	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	VESSEL	
Sound	<input checked="" type="radio"/> FAIR · Attn		VESSEL	<input checked="" type="radio"/> FAIR · Attn *2
Oil	<input checked="" type="radio"/> FAIR · Attn		REAR GATE TYPE	NORMAL · L-GATE (FLAT)
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		REAR GATE	<input checked="" type="radio"/> FAIR · Attn
US EPA	YES · <input checked="" type="radio"/> NO		UNDERCARRIAGE: See Photos. 写真参照	
OPERATION PUMP			RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
Sound	<input checked="" type="radio"/> FAIR · Attn		COMMENT	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		ヒーター&クーラー送風NG HEATER & COOLER: NOT BLOWING AIR	
Power	<input checked="" type="radio"/> FAIR · Attn		*1 HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION	
COOLING SYSTEM			*2 穴、変形あり HOLES, A LITTLE DEFORMED	
Radiator	<input checked="" type="radio"/> FAIR · Attn			
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn			
TRANSMISSION & TRAVEL				
T/M TYPE	<input checked="" type="radio"/> PS · DD *1	No. OF GEARS	2	GEARS
Transmission	<input checked="" type="radio"/> FAIR · Attn			
Travel	<input checked="" type="radio"/> FAIR · Attn			
Swing	FAIR · Attn			
Articulate	FAIR · Attn			
FOOT BRAKE	FAIR · Attn			
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn			
INTERIOR See Photos. 写真参照				
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れあり HUGE CUTS		
Inside Cover	<input checked="" type="radio"/> FAIR · Attn			
Glasses	<input checked="" type="radio"/> FAIR · Attn			
AirCon	A/C · <input checked="" type="radio"/> H/C · H only · C only · None		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。