

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/10/15	MAKE	HITACHI	MODEL	LX20-2
SERIAL	40E-2005			STAMP	F23-2005
HR METER	5596	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP NONE			TIRE SIZE	12.5/70-16 6PR

	ENGINE : MODEL	S/N
Oil leakage	FAIR · Attn	*1
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · DD	
Transmission	FAIR · Attn	油漏れ小 OIL LEAKING
Travel	FAIR · Attn	旋回時異音あり NOISES WHEN TURNING
FOOT BRAKE	FAIR · Attn	ペダル戻り悪い PEDAL: HARD TO RETURN
PARKING BRAKE	FAIR · Attn	*2
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · Attn	破れあり CUTS
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
FRONT & CYLINDERS		
Arm	FAIR · Attn	
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	*3
Articulate	FAIR · Attn	ガタあり LOOSE

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
STEARING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES · OTHER
BLADE	YES · NO Piping for Tilt YES · NO
COMMENT	
操作レバー一杯で負荷がかかるとE/Gが止まる ENGINE STALLING WITH THE ENGINE LOAD INCREASING	
*1 ヘッドカバー周り油漏れ小 AROUND HEAD COVER: OIL LEAKING	
*2 解除ノブ固着気味 RELEASING SWITCH: A LITTLE STUCK	
*3 コンクリ付着、腐食、穴あり *3 CONCRETE STAINS, CORRODED & MUCH HUGE HOLES	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。