

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/24	MAKE	SUMITOMO	MODEL	SH120-3
SERIAL	120A3-6956		STAMP	120A3-6956	
HR METER	7456	HR	YEAR	2007	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL	S/N
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO

MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn

COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn

OPERATING SYSTEM	
Swing	FAIR · Attn
Travel	FAIR · Attn

INTERIOR	See Photos. 写真参照
Operator's Seat	FAIR · Attn 破れあり CUTS
Inside Cover	FAIR · Attn *1
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None

BOOM / ARM / BKT	
Boom	FAIR · Attn
Boom Cylinder	FAIR · Attn
Arm	FAIR · Attn
Arm Cylinder	FAIR · Attn
BKT	FAIR · Attn ガタあり LOOSE
BKT Cylinder	FAIR · Attn

UNDERCARRIAGE :	See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

COMMENT
左キャリアローラー曲がりあり LEFT CARRIER ROLLER: BENT

BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi

COMMENT
*1 ドアなし INSIDE COVER OF AROUND DOOR KNOB: MISSING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。