

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/10/2	MAKE	CAT	MODEL	312E-2
SERIAL	CAT0312EAGAC01612		STAMP	CAT0312EAGAC01612	
HR METER	9630 / 9649	HR	YEAR	2015	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

<b>ENGINE : MODEL C4.4 S/N</b> Oil leakage FAIR · Attn Blow-By FAIR · Attn A LITTLE · MIDDLE · SEVERE Sound FAIR · Attn Oil FAIR · Attn Exhaust Color FAIR · Attn US EPA YES · NO <b>MAIN PUMP</b> Sound FAIR · Attn Oil leakage FAIR · Attn Power FAIR · Attn <b>COOLING SYSTEM</b> Radiator FAIR · Attn Oil Cooler FAIR · Attn <b>OPERATING SYSTEM</b> Swing FAIR · Attn ガタあり SWING: LOOSE Travel FAIR · Attn <b>INTERIOR See Photos. 写真参照</b> Operator's Seat FAIR · Attn Inside Cover FAIR · Attn Glasses FAIR · Attn AirCon A/C · H/C · H only · C only · None <b>BOOM / ARM / BKT</b> Boom FAIR · Attn Boom Cylinder FAIR · Attn Arm FAIR · Attn ガタあり LOOSE Arm Cylinder FAIR · Attn BKT FAIR · Attn BKT Cylinder FAIR · Attn	<b>UNDERCARRIAGE : See Photos. 写真参照</b> RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3 <b>COMMENT</b>        BKT STD / SLOPE / NARROW / SKELETON / OTHER ( ) Lever LONG · WRIST Multi MULTI · 2 · NO ARM-CRANE YES · NO BLADE YES · NO OFFSET YES · NO OFFSET Cylinder FAIR · Attn Piping YES · NO Breaker only Multi *1 <b>COMMENT</b> *1 左右配管欠 PIPES: MISSING         RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
---	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。