

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/18	MAKE	HITACHI	MODEL	ZX350LCH-5B
SERIAL	HCMDDDA3V00070323		STAMP	HCMDDDA3V00070323	
HR METER	4301	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL 6HK1 S/N 578076

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

Operator's Seat	FAIR	Attn	穴あり HOLES
Inside Cover	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

COMMENT

BKT (STD) / SLOPE / NARROW / SKELETON / OTHER ()

Lever LONG · (WRIST)

Multi MULTI · 2 · (NO)

ARM-CRANE YES · (NO)

BLADE YES · (NO)

OFFSET YES · (NO)

OFFSET Cylinder FAIR · Attn

Piping YES · (NO) Breaker only · Multi

COMMENT

左サイドカバー変形あり、ラッチ掛からない

LEFT SIDE COVER: DISTORTED, LATCH: UNABLE TO WORK

COMMENT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。