

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/10/16	MAKE	KOMATSU	MODEL	PC200-8N1
SERIAL	354478		STAMP	KMTPC197E02354478	
HR METER	8648	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR · <input checked="" type="radio"/> Attn *1	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
<b>MAIN PUMP</b>		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	FAIR · <input checked="" type="radio"/> Attn	破れあり TORN
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b>	
左右シューアジャスタースプリング折損あり ADJUSTER CYLINDER SPRINGS: BROKEN	
BKT	STD · <input checked="" type="radio"/> SLOPE · NARROW / SKELETON / OTHER ( )
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="" type="radio"/> NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO · <input checked="" type="radio"/> Breaker only · Multi *2
<b>COMMENT</b>	
E/Gフードダンパー不良 ENGINE HOOD DAMPER: MALFUNCTION 作動油タンク周り油漏れ小 AROUND HYDRAULIC OIL TANK: OIL LEAKING *1 ヘッドカバー周り油漏れ小 AROUND HEAD COVER: OIL LEAKING *2 配管操作ペダル固定あり PEDAL: LOCKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。