INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

| INSPECTION DATE | | 2024/9/19 MAKE | | | MOROOKA | | | MODEL | M | IST-1500VD | |
|---------------------------|-------------|----------------|---------|----------------|---------|--|----------|---------------------|---------------|------------------|---------|
| SERIAL | 153339 | | | | | STAMP | | 153339 | | | |
| HR METER | 8339 HR | | | Odometer | | | | m YEAR | | | YR |
| CAB/CNP | ROPS CA | AB CAB | ROPS | S CNP / CNP / | / NONE | SHOE | | 700R | TIRE | | |
| ENGINE : | l | MAIN FRAME | | | | | | | | | |
| Oil leakage | FAIR · Attn | | | | | MAIN FLAME FAIR • Attn | | | | | |
| Blow-By | FAIR · Attn | A LITTLE | · MIDDL | E · SEVERE | | VESSEL | • | | | | |
| Sound | FAIR · Attn | | | | | VESSE | L | FAIR • Attn | 穴あり(| CRACKED | |
| Oil | FAIR · Attn | | | | | REAR GATE | TYPK | NORMA | L)• L- | -GATE (FLAT) | |
| Exhaust Color | FAIR · Attn | | | | | REAR G | ATE | FAIR • Attn | | | |
| US EPA | YES · NO | | | | | UNDERCARRIAGE: See Photos. 写真参照 | | | | | |
| OPERATION PUMP | | | | | | RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | | | |
| Sound | FAIR · Attn | | | | | COMMENT | Γ | | | | |
| Oil leakage | FAIR · Attn | | | | | バッテリー液ラ | シンプ点が | けあり WARNI | NG LAMP FO | OR BATTERY LIQ | UID: ON |
| Power | FAIR · Attn | | | | | A/C効かな | il A | /C: MALFL | INCTION | | |
| COOLING SYSTEM | | | | | | | | | | | |
| Radiator | FAIR · Attn | | | | | | | | | | |
| Oil Cooler | FAIR · Attn | | | | | | | | | | |
| TRANSMISSION & TRAVEL | | | | | | | | | | | |
| T/M TYPE | PS) · DD | | | No. OF GEARS 2 | GEARS | | | | | | |
| Transmission | FAIR · Attn | | | | | | | | | | |
| Travel | FAIR · Attn | | | | | | | | | | |
| Swing | FAIR · Attn | | | | | | | | | | |
| Articulate | FAIR · Attn | | | | | | | | | | |
| FOOT BRAKE | FAIR · Attn | | | | | | | | | | |
| PARKING BRAKE | FAIR · Attn | | | | | | | | | | |
| INTERIOR See Photos. 写真参照 | | | | | | | | | | | |
| Operator's Seat | FAIR · Attn | 穴あり H | OLES | | | | | | | | |
| Inside Cover | FAIR · Attn | | | | | | | | | | |
| Glasses | FAIR · Attn | | | | | | | | | | |
| AirCon | A/C). | H/C • | H only | • C only • | None | RUST of BODY | (5: NONE | , 4: A LITTLE, 3: I | MIDDLE, 2: MU | CH, 1: CORRODED) | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。