

INSPECTION SHEET 検品書
 FORK LIFT フォークリフト

| | | | | | |
|--------------------|---------------------------|------|----------|-----------|--------------------|
| INSPECTION DATE | 2024/9/25 | MAKE | TCM | MODEL | FG20N16 |
| SERIAL | 20N10257 | | STAMP | F70-10257 | |
| HR METER | 6874 | HR | Odometer | - | km YEAR YR |
| CAB/CNP | CAB | / | CNP | / | NONE |
| TIRE SIZE | F: 5.50-15/4.50 R: 6.00-9 | | | | |
| MAX LIFTING HEIGHT | 3.0 | m | VIEW | MONO | FORK LENGTH 920 mm |
| FORK SPEC | ヒンジドフォーク HINGED FORK | | | | |

| | | |
|----------------------------------|------|---------------------------------|
| ENGINE : MODEL | | S/N |
| Oil leakage | FAIR | Attn |
| Blow-By | FAIR | Attn A LITTLE · MIDDLE · SEVERE |
| Sound | FAIR | Attn |
| Oil | FAIR | Attn |
| Exhaust Color | FAIR | Attn |
| US EPA | YES | NO |
| OPERATION PUMP | | |
| Sound | FAIR | Attn |
| Oil leakage | FAIR | Attn |
| Power | FAIR | Attn |
| COOLING SYSTEM | | |
| Radiator | FAIR | Attn |
| Oil Cooler | FAIR | Attn |
| TRANSMISSION & TRAVEL | | |
| T/M TYPE | PS | DD |
| Transmission | FAIR | Attn |
| Travel | FAIR | Attn |
| FOOT BRAKE | FAIR | Attn |
| PARKING BRAKE | FAIR | Attn |
| INTERIOR See Photos. 写真参照 | | |
| Operator's Seat | FAIR | Attn |
| Inside Cover | FAIR | Attn |
| Glasses | FAIR | Attn |
| AirCon | A/C | H/C H only C only None |
| HYDRAULICS | | |
| MAST Cylinder | FAIR | Attn |
| TILT Cylinder | FAIR | Attn |

| | |
|--|---|
| UNDERCARRIAGE : See Photos. 写真参照 | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
| COMMENT | |
| Fノーパンクタイヤ FRONT TIRES: SOLID | |
| チルトレバー戻り悪い TILT LEVER: HARD TO RETURN | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。