

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2024/9/24	MAKE	HITACHI	MODEL	CS125
SERIAL	8AXP010287		STAMP	125-0287	
HR METER	3231	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	-

ENGINE : MODEL	S/N
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
OPERATION PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS · DD
Transmission	FAIR · Attn
Travel	FAIR · Attn
FOOT BRAKE	FAIR · Attn
PARKING BRAKE	FAIR · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	FAIR · Attn 破れあり CUTS
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
OTHERS	
Vibratory	FAIR · Attn
Watering	FAIR · Attn *1
Articulate	FAIR · Attn シリンダー油漏れ小 CYLINDER: OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
燃料計不良 FUEL GAUGE: MALFUNCTION	
*1 フィルター破損あり、散水不良	
*1 WATERING FILTER: BROKEN, MALFUNCTION TO WATER	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。