

**INSPECTION SHEET 検品書  
EXCAVATOR バックホー**

INSPECTION DATE	2024/9/25	MAKE	KOMATSU	MODEL	PC18MR-3
SERIAL	22069		STAMP	KMTPC206C04022069	
HR METER	1837	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE		SHOE	230G PADS	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
<b>MAIN PUMP</b>		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
<b>OPERATING SYSTEM</b>		
Swing	<u>FAIR</u> · Attn	ガタあり SWING: LOOSE
Travel	<u>FAIR</u> · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	<u>FAIR</u> · Attn	破れあり CUTS
Inside Cover	<u>FAIR</u> · Attn	
Glasses	<u>FAIR</u> · Attn	
AirCon	A/C · H/C · H only · C only · <u>None</u>	
<b>BOOM / ARM / BKT</b>		
Boom	<u>FAIR</u> · Attn	ガタあり LOOSE
Boom Cylinder	<u>FAIR</u> · Attn	
Arm	<u>FAIR</u> · Attn	
Arm Cylinder	<u>FAIR</u> · Attn	
BKT	<u>FAIR</u> · Attn	
BKT Cylinder	<u>FAIR</u> · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b> クローラー伸縮OK VARIABLE WIDTH UNDERCARRIAGE	
BKT <u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ( )	
Lever LONG · <u>WRIST</u>	
Multi <u>MULTI</u> · 2 · NO	
ARM-CRANE YES · <u>NO</u>	
BLADE <u>YES</u> · NO	
OFFSET YES · <u>NO</u>	
OFFSET Cylinder FAIR · Attn	
Piping YES · <u>NO</u> Breaker only · Multi	
<b>COMMENT</b>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。