

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/9/27	MAKE	HITACHI	MODEL	LX110-7		
SERIAL	RYU4F200J00003510			STAMP	S26-03510		
HR METER	8365	HR	Odometer	—	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	17.5-25 (SNOW, SPIKE)		

ENGINE : MODEL						6BG1		S/N		211435	
Oil leakage		FAIR		Attn							
Blow-By		FAIR		Attn		A LITTLE ・ MIDDLE ・ SEVERE					
Sound		FAIR		Attn							
Oil		FAIR		Attn							
Exhaust Color		FAIR		Attn							
US EPA		YES		NO							
OPERATION PUMP											
Sound		FAIR		Attn							
Oil leakage		FAIR		Attn							
Power		FAIR		Attn							
COOLING SYSTEM											
Radiator		FAIR		Attn							
Oil Cooler		FAIR		Attn							
TRANSMISSION & TRAVEL											
T/M TYPE		PS		DD							
Transmission		FAIR		Attn							
Travel		FAIR		Attn							
FOOT BRAKE		FAIR		Attn							
PARKING BRAKE		FAIR		Attn							
INTERIOR See Photos. 写真参照											
Operator's Seat		FAIR		Attn		汚れあり DIRTY					
Inside Cover		FAIR		Attn		破れあり CUT					
Glasses		FAIR		Attn							
AirCon		A/C		H/C		H only		C only		None	
FRONT & CYLINDERS											
Arm		FAIR		Attn							
Bell crank		FAIR		Attn							
Bucket		FAIR		Attn							
Articulate		FAIR		Attn							
UNDERCARRIAGE :										See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)									3		
COMMENT											
下周り油漏れあり BOTTOM: OIL LEAKING											
STEERING TYPE										WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL		YES		NO							
ATTACHMENTS											
STD BKT		YES		OTHER							
BLADE		YES		NO		Piping for Tilt		YES		NO	
COMMENT											
操作弁シール油漏れあり CONTROL VALVE SEAL: OIL LEAKING											
付属品: マルチプラウ MULTI PLOW AS SPARE											
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)										3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。