

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/10/4	MAKE	FURUKAWA	MODEL	FL310-3
SERIAL	RYU4F000J00000529			STAMP	S50-00529
HR METER	18137	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	16.9-24	

<p>ENGINE : MODEL S/N</p> <p>Oil leakage <input type="radio"/> FAIR · Attn</p> <p>Blow-By <input type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE</p> <p>Sound <input type="radio"/> FAIR · Attn</p> <p>Oil <input type="radio"/> FAIR · Attn</p> <p>Exhaust Color <input type="radio"/> FAIR · Attn</p> <p>US EPA YES · <input checked="" type="radio"/> NO</p> <p>OPERATION PUMP</p> <p>Sound <input type="radio"/> FAIR · Attn</p> <p>Oil leakage <input type="radio"/> FAIR · Attn</p> <p>Power <input type="radio"/> FAIR · Attn</p> <p>COOLING SYSTEM</p> <p>Radiator <input type="radio"/> FAIR · Attn</p> <p>Oil Cooler <input type="radio"/> FAIR · Attn</p> <p>TRANSMISSION & TRAVEL</p> <p>T/M TYPE <input checked="" type="radio"/> PS · DD</p> <p>Transmission <input type="radio"/> FAIR · Attn</p> <p>Travel <input type="radio"/> FAIR · Attn</p> <p>FOOT BRAKE <input type="radio"/> FAIR · Attn</p> <p>PARKING BRAKE <input type="radio"/> FAIR · Attn</p> <p>INTERIOR See Photos. 写真参照</p> <p>Operator's Seat <input type="radio"/> FAIR · Attn 破れあり HUGE CUTS</p> <p>Inside Cover <input type="radio"/> FAIR · Attn</p> <p>Glasses <input type="radio"/> FAIR · Attn</p> <p>AirCon <input checked="" type="radio"/> A/C · H/C · H only · C only · None</p> <p>FRONT & CYLINDERS</p> <p>Arm <input type="radio"/> FAIR · Attn *1</p> <p>Bell crank <input type="radio"/> FAIR · Attn</p> <p>Bucket <input type="radio"/> FAIR · Attn</p> <p>Articulate <input type="radio"/> FAIR · Attn</p>	<p>UNDERCARRIAGE : See Photos. 写真参照</p> <p>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) <input type="text" value="4"/></p> <p>COMMENT</p> <p>STEERING TYPE <input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / LEVER STEERING</p> <p>RIDE CONTROL YES · <input checked="" type="radio"/> NO</p> <p>ATTACHMENTS</p> <p>STD BKT <input type="radio"/> YES · OTHER</p> <p>BLADE YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO</p> <p>COMMENT</p> <p>*1 左シリンダー油漏れ小 LEFT CYLINDER: OIL LEAKING</p> <p>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) <input type="text" value="4"/></p>
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。