

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/10/25	MAKE	KATO	MODEL	KR-10H-L II
SERIAL No.	PLATE :	3910655		STAMP :	KR102-0655
HR METER	23830	HR	Odometer	135984	km
TIRE SIZE	275/80R22.5		YEAR	2000	YR

ENGINE : MODEL		S/N
Oil leakage	FAIR <input checked="" type="radio"/> Attn	*1
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	
OPERATION PUMP		
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	
Power	FAIR <input checked="" type="radio"/> Attn	
COOLING SYSTEM		
Radiator	FAIR <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	
OPERATING SYSTEM		
Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input checked="" type="radio"/> Attn	
Travel	FAIR <input checked="" type="radio"/> Attn	
TRANSMISSION		
Transmission	FAIR <input checked="" type="radio"/> Attn	
No. OF GEARS	3	GEARS
No. of DRIVE WHEELS	4	WD
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	
Inside Cover	FAIR <input checked="" type="radio"/> Attn	
Glasses	FAIR <input checked="" type="radio"/> Attn	
AirCon	A/C <input checked="" type="radio"/> H/C · H only · C only · None	
COMMENT		

BOOM	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn
JIB	YES <input checked="" type="radio"/> NO
JIB TYPE	STD <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO
HOOK	10t, BALL
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
OUTRIGGERS	
OUTRIGGERS	X · H <input checked="" type="radio"/>
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn
COMMENT	
*1 E/Gヘッド油漏れあり CYLINDER HEAD: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。