

INSPECTION SHEET 検品書
 ASPHALT FINISHER アスファルトフィニッシャー

INSPECTION DATE	2024/10/3	MAKE	SUMITOMO	MODEL	HA60W-5
SERIAL	A60A5-0104		STAMP	A60A5-0104	
HR METER	1504	HR	YEAR	YR	
SHOE		TIRE (REAR)	15.5R25	MAX PAVING WIDTH	6200 mm

ENGINE : MODEL	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
US EPA	YES · <input checked="" type="radio"/> NO
OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
OPERATING SYSTEM	
TRAVEL	<input checked="" type="radio"/> FAIR · Attn
SCREED(R)	<input checked="" type="radio"/> FAIR · Attn
SCREED(L)	<input checked="" type="radio"/> FAIR · Attn
VIBRATION	<input checked="" type="radio"/> FAIR · Attn
TAMPER	<input checked="" type="radio"/> FAIR · Attn
SPREADER(R)	<input checked="" type="radio"/> FAIR · Attn
SPREADER(L)	<input checked="" type="radio"/> FAIR · Attn
HOPPER(R)	<input checked="" type="radio"/> FAIR · Attn
HOPPER(L)	<input checked="" type="radio"/> FAIR · Attn
FEEDER	<input checked="" type="radio"/> FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
シート外れあり SEAT: COME OFF 左右サイドプレートシリンダーサビ、傷あり SIDE PLATE CYLINDERS: RUSTY, SCRATCHED 右側サイドプレートシリンダー動作時油漏れ大 RIGHT SIDE PLATE CYLINDER: SEVERE OIL LEAKING DURING WORKING	
SCREED WIDTH	
MAIN SCREED	2.7 m
WITH AUTO-WIDENER	6.2 m
WITH EXTENSION	m
LEVEL SENSOR	YES · <input checked="" type="radio"/> NO
COMMENT	
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。