

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/10/22	MAKE	CAT	MODEL	308C
SERIAL	CAT0308CECPE01076		STAMP	CAT0308CECPE01076	
HR METER	2477 STOP	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	450G PADS		

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR · <input checked="" type="radio"/> Attn	*1
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
<b>MAIN PUMP</b>		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	FAIR · <input checked="" type="radio"/> Attn	破れあり CUT
Inside Cover	FAIR · <input checked="" type="radio"/> Attn	*2
Glasses	FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>		
Boom	FAIR · <input checked="" type="radio"/> Attn	ガタあり LOOSE
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · <input checked="" type="radio"/> Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b>	
左走行モーター周り油漏れ小 AROUND LEFT TRAVEL MOTOR: OIL LEAKING	
BKT <input checked="" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / <input type="radio"/> OTHER ( )	
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO
BLADE	<input checked="" type="radio"/> YES · NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi
<b>COMMENT</b>	
HRメーター故障あり HR METER: MALFUNCTION チャージランプ点灯あり CHARGE LAMP: ON ファンベルト鳴きあり FAN BELT: NOISES ドア変形、最後まで閉まらない DOOR: DISTORTED, UNABLE TO SHUT *1 ヘッドカバー周り油漏れ小 AROUND HEAD COVER: OIL LEAKING *2 ドアなし、安全レバーカバー破損あり *2 INSIDE DOOR KNOB COVER: MISSING, SAFETY LEVER COVER: BROKEN	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。