

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/8	MAKE	SUMITOMO	MODEL	SH40JX
SERIAL	040JX-0276		STAMP	040JX-0276	
HR METER	5447	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	400R	

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
MAIN PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
OPERATING SYSTEM		
Swing	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · <u>Attn</u>	破れあり SEAT COVER: PARTLY PEELED
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · <u>None</u>	
BOOM / ARM / BKT		
Boom	FAIR · <u>Attn</u>	ガタあり LOOSE
Boom Cylinder	<u>FAIR</u> · Attn	
Arm	FAIR · <u>Attn</u>	ガタあり LOOSE
Arm Cylinder	<u>FAIR</u> · Attn	
BKT	FAIR · <u>Attn</u>	ガタあり LOOSE
BKT Cylinder	<u>FAIR</u> · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD · <u>SLOPE</u> · NARROW / SKELETON / OTHER ()
Lever	LONG · <u>WRIST</u>
Multi	MULTI · 2 · <u>NO</u>
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
COMMENT	
スイングシリンダー油漏れ小 SWING CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。