INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2024/10/18	MAKE	KOMATSU	MODEL	FD100-5
SERIAL	4006	STAMP	M114-4006		
HR METER	397 HR	Odometer	- km	YEAR	YR
CAB/CNP	CAB / (CNP) / NONE	TIRE SIZE	9.00-20		
MAX LIFTING HEIGHT	3.0 m	(VIEW) / MONO	FORK LENGTH	1200 mm	
FORK SPEC					

ENGINE : MODEL S/N		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
FOOT BRAKE	(FAIR) · Attn	
PARKING BRAKE	(FAIR) · Attn	
INTERIOR	See Photos. 写真参照	
Operator's Seat	(FAIR) · Attn	破れ大 DAMAGED
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
HYDRAULICS		
MAST Cylinder	(FAIR) · Attn	
TILT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。