

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/9/30	MAKE	HITACHI	MODEL	ZX200-3
SERIAL	HCM1U100P00214729		STAMP	HCM1U100P00214729	
HR METER	UNKNOWN	HR	YEAR	YR	
CAB/CNP	ROPS CAB <input checked="" type="checkbox"/> / <input type="checkbox"/> ROPS CNP / CNP / NONE	SHOE		800G	

ENGINE : MODEL 4HK1 S/N 460895	
Oil leakage	<input checked="" type="checkbox"/> FAIR · Attn
Blow-By	<input checked="" type="checkbox"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="checkbox"/> FAIR · Attn
Oil	<input checked="" type="checkbox"/> FAIR · Attn
Exhaust Color	<input checked="" type="checkbox"/> FAIR · Attn
US EPA	<input checked="" type="checkbox"/> YES · NO
MAIN PUMP	
Sound	<input checked="" type="checkbox"/> FAIR · Attn
Oil leakage	<input checked="" type="checkbox"/> FAIR · Attn
Power	<input checked="" type="checkbox"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="checkbox"/> FAIR · Attn
Oil Cooler	<input checked="" type="checkbox"/> FAIR · Attn
OPERATING SYSTEM	
Swing	<input checked="" type="checkbox"/> FAIR · Attn ブレーキ甘い BRAKE: LOOSE
Travel	<input checked="" type="checkbox"/> FAIR · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	<input checked="" type="checkbox"/> FAIR · Attn 破れ大 TORN
Inside Cover	<input checked="" type="checkbox"/> FAIR · Attn
Glasses	<input checked="" type="checkbox"/> FAIR · Attn
AirCon	<input checked="" type="checkbox"/> A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	<input checked="" type="checkbox"/> FAIR · Attn
Boom Cylinder	<input checked="" type="checkbox"/> FAIR · Attn
Arm	<input checked="" type="checkbox"/> FAIR · Attn
Arm Cylinder	<input checked="" type="checkbox"/> FAIR · Attn
BKT	<input checked="" type="checkbox"/> FAIR · <input checked="" type="checkbox"/> Attn 穴、ガタあり HUGE HOLE, LOOSE
BKT Cylinder	<input checked="" type="checkbox"/> FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
スプロケット摩耗あり SPROCKETS: WORN	
BKT <input checked="" type="checkbox"/> STD / <input type="checkbox"/> SLOPE / <input type="checkbox"/> NARROW / <input type="checkbox"/> SKELETON / OTHER ()	
Lever	LONG · <input checked="" type="checkbox"/> WRIST
Multi	MULTI · 2 · <input checked="" type="checkbox"/> NO
ARM-CRANE	YES · <input checked="" type="checkbox"/> NO
BLADE	YES · <input checked="" type="checkbox"/> NO
OFFSET	YES · <input checked="" type="checkbox"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · <input checked="" type="checkbox"/> NO Breaker only · Multi
COMMENT	
A/Cベルト欠 A/C: NO BELT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。