

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/9/27	MAKE	HITACHI	MODEL	ZX225USR-3
SERIAL	HCM1U500C00200835		STAMP	HCM1U500C00200835	
HR METER	8327	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b>	4HK1	<b>S/N</b>	402455
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	<input checked="" type="radio"/> YES	<input type="radio"/> NO	
<b>MAIN PUMP</b>			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	
<b>COOLING SYSTEM</b>			
Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	
<b>OPERATING SYSTEM</b>			
Swing	<input checked="" type="radio"/> FAIR	Attn ガタあり SWING: LOOSE	
Travel	<input checked="" type="radio"/> FAIR	Attn	
<b>INTERIOR See Photos. 写真参照</b>			
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	
Inside Cover	<input checked="" type="radio"/> FAIR	Attn	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	<input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None	
<b>BOOM / ARM / BKT</b>			
Boom	<input checked="" type="radio"/> FAIR	Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn	
Arm	<input checked="" type="radio"/> FAIR	Attn ガタあり LOOSE	
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn	
BKT	<input checked="" type="radio"/> FAIR	Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
BKT	<input checked="" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER ( )
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="" type="radio"/> NO
ARM-CRANE	<input checked="" type="radio"/> YES · <input type="radio"/> NO MLクレーン故障警告表示あり WARNING DISPLAY
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · <input type="radio"/> NO Breaker only · <input checked="" type="radio"/> Multi 5
<b>COMMENT</b>	
バックモニター不良 BACK MONITOR: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。