

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

| | | | | | |
|-----------------|---|-------------|-------------|---------|---------|
| INSPECTION DATE | 2024/9/24 | MAKE | KOMATSU | MODEL | WA100-8 |
| SERIAL | 91087 | STAMP | WA138-91087 | | |
| HR METER | 146 | HR Odometer | 684 | km YEAR | YR |
| CAB/CNP | <u>ROPS CAB</u> / CAB / ROPS CNP / CNP / NONE | TIRE SIZE | 16.9-24 | | |

| | | |
|----------------------------------|---|----------------------------|
| ENGINE : MODEL | | S/N |
| Oil leakage | <u>FAIR</u> · Attn | |
| Blow-By | <u>FAIR</u> · Attn | A LITTLE · MIDDLE · SEVERE |
| Sound | <u>FAIR</u> · Attn | |
| Oil | <u>FAIR</u> · Attn | |
| Exhaust Color | <u>FAIR</u> · Attn | |
| US EPA | YES · <u>NO</u> | |
| OPERATION PUMP | | |
| Sound | <u>FAIR</u> · Attn | |
| Oil leakage | <u>FAIR</u> · Attn | |
| Power | <u>FAIR</u> · Attn | |
| COOLING SYSTEM | | |
| Radiator | <u>FAIR</u> · Attn | |
| Oil Cooler | <u>FAIR</u> · Attn | |
| TRANSMISSION & TRAVEL | | |
| T/M TYPE | <u>PS</u> · DD | |
| Transmission | <u>FAIR</u> · Attn | |
| Travel | <u>FAIR</u> · Attn | |
| FOOT BRAKE | <u>FAIR</u> · Attn | |
| PARKING BRAKE | <u>FAIR</u> · Attn | |
| INTERIOR See Photos. 写真参照 | | |
| Operator's Seat | <u>FAIR</u> · Attn | |
| Inside Cover | <u>FAIR</u> · Attn | |
| Glasses | <u>FAIR</u> · Attn | |
| AirCon | <u>A/C</u> · H/C · H only · C only · None | |
| FRONT & CYLINDERS | | |
| Arm | <u>FAIR</u> · Attn | |
| Bell crank | <u>FAIR</u> · Attn | |
| Bucket | <u>FAIR</u> · Attn | |
| Articulate | <u>FAIR</u> · Attn | |

| | | | |
|---|---|------------------|-----------------|
| UNDERCARRIAGE : | | See Photos. 写真参照 | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | 4 | |
| COMMENT | | | |
| <hr/> <hr/> <hr/> <hr/> | | | |
| STEERING TYPE | <u>WHEEL STEERING</u> / COMMAND STEERING / LEVER STEERING | | |
| RIDE CONTROL | <u>YES</u> · NO | | |
| ATTACHMENTS | | | |
| STD BKT | <u>YES</u> · OTHER | | |
| BLADE | YES · <u>NO</u> | Piping for Tilt | YES · <u>NO</u> |
| COMMENT | | | |
| <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> <hr/> | | | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | 4 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。