

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2025/5/27	MAKE	HITACHI	MODEL	ZC35T-5
SERIAL	HCMTDJA0C00050121			STAMP	HCMTDJA0C00050121
HR METER	1034	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>			TIRE SIZE	-

ENGINE : MODEL D1703 S/N 7JK3010		UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage	<u>FAIR</u> · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4	
Blow-By	<u>FAIR</u> · Attn	TIRE WEAR FAIR · WORN · UNEVEN WEAR	
Sound	<u>FAIR</u> · Attn	COMMENT	
Oil	<u>FAIR</u> · Attn	*1 F1ヶ所、R1ヶ所目詰まり	
Exhaust Color	<u>FAIR</u> · Attn	*1 SOME FRONT WATERING NOZZLE & SOME REAR WATERING NOZZLE: CLOGGED	
US EPA	YES · <u>NO</u>		
OPERATION PUMP			
Sound	<u>FAIR</u> · Attn		
Oil leakage	<u>FAIR</u> · Attn		
Power	<u>FAIR</u> · Attn		
COOLING SYSTEM			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	<u>PS</u> · DD		
Transmission	<u>FAIR</u> · Attn		
Travel	<u>FAIR</u> · Attn		
FOOT BRAKE	<u>FAIR</u> · Attn		
PARKING BRAKE	<u>FAIR</u> · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	<u>CLEAN</u> · FAIR · DIRTY		
Operator's Seat	<u>FAIR</u> · Attn		
Glasses	<u>FAIR</u> · Attn		
AirCon	A/C · H/C · H only · C only · <u>None</u>		
OTHERS			
Vibratory	<u>FAIR</u> · Attn		
Watering	<u>FAIR</u> · Attn	*1	
Articulate	<u>FAIR</u> · Attn		
		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。