

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/9/19	MAKE	HITACHI	MODEL	ZX40U-5A
SERIAL	HMAEAA0V00031901		STAMP	HMAEAA0V00031901	
HR METER	4719	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	400G PADS	

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · Attn	
US EPA	<input type="radio"/> YES · <input checked="" type="radio"/> NO	
MAIN PUMP		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · Attn	
Power	<input type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Swing	<input type="radio"/> FAIR · Attn	
Travel	<input type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	<input type="radio"/> FAIR · Attn	
Inside Cover	<input type="radio"/> FAIR · Attn	
Glasses	<input type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · <input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · None	
BOOM / ARM / BKT		
Boom	<input type="radio"/> FAIR · Attn	
Boom Cylinder	<input type="radio"/> FAIR · Attn	
Arm	<input type="radio"/> FAIR · Attn	
Arm Cylinder	<input type="radio"/> FAIR · Attn	
BKT	<input type="radio"/> FAIR · Attn	
BKT Cylinder	<input type="radio"/> FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	<input checked="" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / <input type="radio"/> OTHER ()
Lever	<input type="radio"/> LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · <input type="radio"/> NO
ARM-CRANE	<input checked="" type="radio"/> YES · <input type="radio"/> NO
BLADE	<input checked="" type="radio"/> YES · <input type="radio"/> NO
OFFSET	<input type="radio"/> YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	<input type="radio"/> FAIR · <input type="radio"/> Attn
Piping	<input type="radio"/> YES · <input checked="" type="radio"/> NO Breaker only · <input type="radio"/> Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。