

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |  |      |         |            |          |
|-----------------|--|------|---------|------------|----------|
| INSPECTION DATE | 2024/10/15                             | MAKE | KOBELCO | MODEL      | SK75SR-3 |
| SERIAL          | YT07-26909                             |      | STAMP   | YT07-26909 |          |
| HR METER        | 3912                                   | HR   | YEAR    | YR         |          |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 450G PADS  |          |

**ENGINE : MODEL** 4LE2 **S/N** 612210

|               |                                       |                                     |                            |
|---------------|---------------------------------------|-------------------------------------|----------------------------|
| Oil leakage   | <input checked="" type="radio"/> FAIR | Attn                                |                            |
| Blow-By       | <input checked="" type="radio"/> FAIR | Attn                                | A LITTLE · MIDDLE · SEVERE |
| Sound         | <input checked="" type="radio"/> FAIR | Attn                                |                            |
| Oil           | <input checked="" type="radio"/> FAIR | Attn                                |                            |
| Exhaust Color | <input checked="" type="radio"/> FAIR | Attn                                |                            |
| US EPA        | YES                                   | <input checked="" type="radio"/> NO |                            |

**MAIN PUMP**

|             |                                       |      |  |
|-------------|---------------------------------------|------|--|
| Sound       | <input checked="" type="radio"/> FAIR | Attn |  |
| Oil leakage | <input checked="" type="radio"/> FAIR | Attn |  |
| Power       | <input checked="" type="radio"/> FAIR | Attn |  |

**COOLING SYSTEM**

|            |                                       |      |  |
|------------|---------------------------------------|------|--|
| Radiator   | <input checked="" type="radio"/> FAIR | Attn |  |
| Oil Cooler | <input checked="" type="radio"/> FAIR | Attn |  |

**OPERATING SYSTEM**

|        |                                       |      |  |
|--------|---------------------------------------|------|--|
| Swing  | <input checked="" type="radio"/> FAIR | Attn |  |
| Travel | <input checked="" type="radio"/> FAIR | Attn |  |

**INTERIOR** See Photos. 写真参照

|                 |                                       |                              |          |
|-----------------|---------------------------------------|------------------------------|----------|
| Operator's Seat | <input checked="" type="radio"/> FAIR | Attn                         | 破れあり CUT |
| Inside Cover    | <input checked="" type="radio"/> FAIR | Attn                         |          |
| Glasses         | <input checked="" type="radio"/> FAIR | Attn                         |          |
| AirCon          | <input checked="" type="radio"/> A/C  | H/C · H only · C only · None |          |

**BOOM / ARM / BKT**

|               |                                       |      |  |
|---------------|---------------------------------------|------|--|
| Boom          | <input checked="" type="radio"/> FAIR | Attn |  |
| Boom Cylinder | <input checked="" type="radio"/> FAIR | Attn |  |
| Arm           | <input checked="" type="radio"/> FAIR | Attn |  |
| Arm Cylinder  | <input checked="" type="radio"/> FAIR | Attn |  |
| BKT           | <input checked="" type="radio"/> FAIR | Attn |  |
| BKT Cylinder  | <input checked="" type="radio"/> FAIR | Attn |  |

**UNDERCARRIAGE :** See Photos. 写真参照

**RUST** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

**COMMENT**

.....

.....

.....

.....

**BKT**  STD / SLOPE / NARROW / SKELETON / OTHER ( )

**Lever** LONG ·  WRIST

**Multi**  MULTI · 2 · NO

**ARM-CRANE**  YES · NO

**BLADE**  YES · NO

**OFFSET** YES ·  NO

**OFFSET Cylinder** FAIR · Attn

**Piping** YES ·  NO Breaker only · Multi

**COMMENT**

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

**RUST of BODY** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。