

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2024/9/24	MAKE	HITACHI	MODEL	ZC35C
SERIAL	HCMTCAA0T00033106		STAMP	HCM8UP00A00033106	
HR METER	1939	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>		TIRE SIZE	9.5/65-15	

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · Attn	
US EPA	YES · <input type="radio"/> NO	
OPERATION PUMP		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · Attn	
Power	<input type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	<input type="radio"/> PS · DD	
Transmission	<input type="radio"/> FAIR · Attn	
Travel	<input type="radio"/> FAIR · Attn	
FOOT BRAKE	<input type="radio"/> FAIR · Attn	
PARKING BRAKE	<input type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	<input type="radio"/> FAIR · Attn	
Inside Cover	<input type="radio"/> FAIR · Attn	
Glasses	<input type="radio"/> FAIR · Attn	
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None	
OTHERS		
Vibratory	<input type="radio"/> FAIR · Attn	
Watering	<input type="radio"/> FAIR · Attn	配管水漏れあり PIPE: WATER LEAKING
Articulate	<input type="radio"/> FAIR · Attn	

UNDERCARRIAGE :	See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。