

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/10/3	MAKE	TADANO	MODEL	TR-100M-1
SERIAL No.	PLATE : FC1210		STAMP : TR100-1210		
HR METER	15926	HR	Odometer	168464	km
TIRE SIZE	11R22.5		YEAR	YR	

ENGINE : MODEL	S/N
Oil leakage	FAIR <input checked="" type="radio"/> Attn *1
Blow-By	FAIR <input checked="" type="radio"/> Attn A LITTLE <input checked="" type="radio"/> MIDDLE <input type="radio"/> SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn
Oil	FAIR <input checked="" type="radio"/> Attn
Exhaust Color	FAIR <input checked="" type="radio"/> Attn 白煙大 MUCH WHITE FUMES

OPERATION PUMP	
Sound	FAIR <input checked="" type="radio"/> Attn
Oil leakage	FAIR <input checked="" type="radio"/> Attn
Power	FAIR <input checked="" type="radio"/> Attn

COOLING SYSTEM	
Radiator	FAIR <input checked="" type="radio"/> Attn
Oil Cooler	FAIR <input checked="" type="radio"/> Attn

OPERATING SYSTEM	
Computer	OK <input checked="" type="radio"/> NG
Swing	FAIR <input checked="" type="radio"/> Attn
Travel	FAIR <input checked="" type="radio"/> Attn

TRANSMISSION	
Transmission	FAIR <input checked="" type="radio"/> Attn
No. OF GEARS	3 GEARS
No. of DRIVE WHEELS	4 WD

INTERIOR See Photos. 写真参照	
Operator's Seat	FAIR <input checked="" type="radio"/> Attn 破れあり CUTS
Inside Cover	FAIR <input checked="" type="radio"/> Attn
Glasses	FAIR <input checked="" type="radio"/> Attn
AirCon	A/C <input checked="" type="radio"/> H/C <input type="radio"/> H only <input type="radio"/> C only <input type="radio"/> None

COMMENT	

BOOM	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn
JIB	YES <input checked="" type="radio"/> NO
JIB TYPE	STD <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO
HOOK	10t, BALL

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

COMMENT	

OUTRIGGERS	
OUTRIGGERS	X <input checked="" type="radio"/> H
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn

COMMENT	
過巻センサー不良 OVERWINDING PREVENTION SENSOR: MALFUNCTION	
*1 E/G下部にじみあり LOWER PART OF ENGINE: OIL OOZING	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。