

INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2024/10/21	MAKE	TCM	MODEL	FD45Z
SERIAL	28A06568		STAMP	F39-06568	
HR METER	9270 STOP HR	Odometer	-	km	YEAR YR
CAB/CNP	CAB / <u>CNP</u> / NONE		TIRE SIZE	F: 7.50-16 14PR / R: 7.00-12/5.00 SOLID	
MAX LIFTING HEIGHT	3.0 m	<u>VIEW</u> MONO	FORK LENGTH	1200 mm	
FORK SPEC	ヒンジフォーク HINGED FORK				

ENGINE : MODEL	S/N
Oil leakage	<u>FAIR</u> · Attn
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn
Oil	<u>FAIR</u> · Attn
Exhaust Color	<u>FAIR</u> · Attn 青白煙あり BLUISH WHITE FUMES
US EPA	YES · <u>NO</u>
OPERATION PUMP	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · Attn
Power	<u>FAIR</u> · Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS · <u>DD</u>
Transmission	<u>FAIR</u> · Attn
Travel	<u>FAIR</u> · Attn
FOOT BRAKE	<u>FAIR</u> · Attn ブレーキ引きずりあり BRAKE: CAUGHT ON
PARKING BRAKE	<u>FAIR</u> · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	<u>FAIR</u> · Attn 破れあり TORN
Inside Cover	<u>FAIR</u> · Attn
Glasses	<u>FAIR</u> · Attn
AirCon	A/C · H/C · H only · C only · <u>None</u>
HYDRAULICS	
MAST Cylinder	<u>FAIR</u> · Attn
TILT Cylinder	<u>FAIR</u> · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
HRメーター故障あり HR METER: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。