

## INSPECTION SHEET 検品書

## ROLLER ローラー

INSPECTION DATE	2024/10/21	MAKE	SAKAI	MODEL	T2		
SERIAL	43156		STAMP	TT1-43156			
HR METER	1481	HR	Odometer	5027	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	14/70-20 12PR		

<b>ENGINE : MODEL</b>		<b>S/N</b>	<b>UNDERCARRIAGE :</b> See Photos. 写真参照
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		<b>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b> 3
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	<b>COMMENT</b> ..... ..... ..... ..... ..... ..... ..... ..... ..... ..... ..... ..... ..... ..... ..... .....
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil	<input checked="" type="radio"/> FAIR · Attn		
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		
US EPA	YES · <input checked="" type="radio"/> NO		
<b>OPERATION PUMP</b>			
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Power	<input checked="" type="radio"/> FAIR · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<input checked="" type="radio"/> FAIR · Attn		
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn		
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	PS · <input checked="" type="radio"/> DD		
Transmission	<input checked="" type="radio"/> FAIR · Attn		
Travel	<input checked="" type="radio"/> FAIR · Attn		
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn		
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn		
<b>INTERIOR</b> See Photos. 写真参照			
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れあり CUT	
Inside Cover	<input checked="" type="radio"/> FAIR · Attn		
Glasses	<input checked="" type="radio"/> FAIR · Attn		
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None		
<b>OTHERS</b>			
Vibratory	<input checked="" type="radio"/> FAIR · Attn		
Watering	<input checked="" type="radio"/> FAIR · Attn		
Articulate	<input checked="" type="radio"/> FAIR · Attn		
<b>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b> 2			

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。