

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/10/17	MAKE	KUBOTA	MODEL	U-30-5
SERIAL	72362		STAMP	72362	
HR METER	2845	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300R	

**ENGINE : MODEL S/N AS0048**

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	<b>NO</b>	

**MAIN PUMP**

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

**COOLING SYSTEM**

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

**OPERATING SYSTEM**

Swing	FAIR	Attn	
Travel	FAIR	Attn	

**INTERIOR See Photos. 写真参照**

Operator's Seat	FAIR	<b>Attn</b>	破れあり TINY CUT
Inside Cover	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · <b>None</b>

**BOOM / ARM / BKT**

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

**UNDERCARRIAGE : See Photos. 写真参照**

**RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)**     **3**

**COMMENT**

右走行モーター周り油漏れ小  
AROUND RIGHT TRAVEL MOTOR: OIL LEAKING

BKT  STD /  SLOPE /  NARROW /  SKELETON /  OTHER ( )

Lever LONG ·  WRIST

Multi  MULTI · 2 · NO

ARM-CRANE YES ·  NO

BLADE  YES · NO

OFFSET YES ·  NO

OFFSET Cylinder FAIR · Attn

Piping  YES · NO Breaker only ·  Multi

**COMMENT**

**RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)**     **3**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。