

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2024/7/31	MAKE	SAKAI	MODEL	SV510D
SERIAL	10131		STAMP	VSV8D-10131	
HR METER	2961	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	23.1-26 8PR	

ENGINE : MODEL	S/N	UNDERCARRIAGE :	See Photos. 写真参照
Oil leakage	FAIR (Attn) *1	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
Blow-By	FAIR (Attn) A LITTLE · MIDDLE · SEVERE	COMMENT	
Sound	FAIR (Attn)	A/C効かない A/C: MALFUNCTION	
Oil	FAIR (Attn)	シフトレバー振動S/Wゴムキャップ破損あり	
Exhaust Color	FAIR (Attn)	RUBBER CAP OF VIBRATION SWITCH AT THE SHIFT LEVER: BROKEN	
US EPA	YES (NO)	*1 E/Gブロック後方油漏れ小	
OPERATION PUMP		*1 REAR PART OF ENGINE BLOCK: OIL LEAKING	
Sound	FAIR (Attn)		
Oil leakage	FAIR (Attn)		
Power	FAIR (Attn)		
COOLING SYSTEM			
Radiator	FAIR (Attn)		
Oil Cooler	FAIR (Attn)		
TRANSMISSION & TRAVEL			
T/M TYPE	PS (DD)		
Transmission	FAIR (Attn)		
Travel	FAIR (Attn)		
FOOT BRAKE	FAIR (Attn)		
PARKING BRAKE	FAIR (Attn)		
INTERIOR		See Photos. 写真参照	
Operator's Seat	FAIR (Attn) 破れあり CUTS		
Inside Cover	FAIR (Attn)		
Glasses	FAIR (Attn)		
AirCon	A/C (H/C · H only · C only · None)		
OTHERS			
Vibratory	FAIR (Attn)		
Watering	FAIR (Attn)		
Articulate	FAIR (Attn)	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。