

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	20214/6/10	MAKE	HITACHI	MODEL	EX120-5E
SERIAL	1E8P053773		STAMP	1E8P053773	
HR METER	10253	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL _____ **S/N** _____

Oil leakage	<input checked="" type="radio"/> FAIR	· Attn	_____
Blow-By	<input checked="" type="radio"/> FAIR	· Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	· Attn	_____
Oil	<input checked="" type="radio"/> FAIR	· Attn	_____
Exhaust Color	<input checked="" type="radio"/> FAIR	· Attn	_____
US EPA	YES	<input checked="" type="radio"/> NO	_____

MAIN PUMP

Sound	<input checked="" type="radio"/> FAIR	· Attn	_____
Oil leakage	<input checked="" type="radio"/> FAIR	· Attn	_____
Power	<input checked="" type="radio"/> FAIR	· Attn	_____

COOLING SYSTEM

Radiator	<input checked="" type="radio"/> FAIR	· Attn	_____
Oil Cooler	<input checked="" type="radio"/> FAIR	· Attn	_____

OPERATING SYSTEM

Swing	<input checked="" type="radio"/> FAIR	· Attn	_____
Travel	<input checked="" type="radio"/> FAIR	· Attn	_____

INTERIOR See Photos. 写真参照

Operator's Seat	<input checked="" type="radio"/> FAIR	· Attn	ひび割れあり CRACKED
Inside Cover	<input checked="" type="radio"/> FAIR	· Attn	ドア無し INSIDE COVER OF DOOR: MISSING
Glasses	<input checked="" type="radio"/> FAIR	· Attn	_____
AirCon	<input checked="" type="radio"/> A/C	· H/C · H only · C only · None	_____

BOOM / ARM / BKT

Boom	<input checked="" type="radio"/> FAIR	· Attn	ガタあり LOOSE
Boom Cylinder	<input checked="" type="radio"/> FAIR	· Attn	*1
Arm	<input checked="" type="radio"/> FAIR	· Attn	ガタあり LOOSE
Arm Cylinder	<input checked="" type="radio"/> FAIR	· Attn	_____
BKT	<input checked="" type="radio"/> FAIR	· Attn	_____
BKT Cylinder	<input checked="" type="radio"/> FAIR	· Attn	_____

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

COMMENT

左右シューリンクブッシュ割れあり SOME PIN BUSHES: BROKEN
右側キャリアローラー曲がり、純正外品装着あり
RIGHT CARRIER ROLLER: BENT, NOT GENUINE

BKT	STD	<input checked="" type="radio"/> SLOPE	NARROW / SKELETON / OTHER ()
-----	-----	--	-------------------------------

Lever	LONG	· <input checked="" type="radio"/> WRIST	_____
-------	------	--	-------

Multi	<input checked="" type="radio"/> MULTI	· 2 · NO	_____
-------	--	----------	-------

ARM-CRANE	YES	<input checked="" type="radio"/> NO	_____
-----------	-----	-------------------------------------	-------

BLADE	YES	<input checked="" type="radio"/> NO	_____
-------	-----	-------------------------------------	-------

OFFSET	YES	<input checked="" type="radio"/> NO	_____
--------	-----	-------------------------------------	-------

OFFSET Cylinder	FAIR	· Attn	_____
-----------------	------	--------	-------

Piping	YES	<input checked="" type="radio"/> NO	Breaker only · Multi
--------	-----	-------------------------------------	----------------------

COMMENT

14mスーパーロング 14m SUPER LONG
*1 右シリンダー油漏れ小 RIGHT CYLINDER: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。