

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/10/3	MAKE	TADANO	MODEL	TR-250M-6
SERIAL No.	PLATE : FB1462		STAMP : TR255-0102		
HR METER	12587	HR	Odometer	88384	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL	S/N
Oil leakage	<input type="radio"/> FAIR · Attn
Blow-By	<input type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn
Oil	<input type="radio"/> FAIR · Attn
Exhaust Color	<input type="radio"/> FAIR · Attn
OPERATION PUMP	
Sound	<input type="radio"/> FAIR · Attn
Oil leakage	<input type="radio"/> FAIR · Attn
Power	<input type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input type="radio"/> FAIR · Attn
Oil Cooler	<input type="radio"/> FAIR · Attn
OPERATING SYSTEM	
Computer	<input checked="" type="radio"/> OK · NG
Swing	<input type="radio"/> FAIR · Attn
Travel	<input type="radio"/> FAIR · Attn
TRANSMISSION	
Transmission	<input type="radio"/> FAIR · Attn
No. OF GEARS	4 GEARS
No. of DRIVE WHEELS	4 WD
INTERIOR See Photos. 写真参照	
Operator's Seat	<input type="radio"/> FAIR · Attn 破れ小 TINY CUT
Inside Cover	<input type="radio"/> FAIR · Attn
Glasses	<input type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
COMMENT	
CAB腐食あり CAB: CORRODED	

BOOM	
No. of Section	4 SECTIONS
CRACK/ENFORCEMENT	<input type="radio"/> FAIR · Attn
DERRICKING CYL.	<input type="radio"/> FAIR · Attn
EXTENSION CYL.	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn 油漏れあり OIL LEAKING
JIB	YES · <input checked="" type="radio"/> NO
JIB TYPE	STD · PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
HOOK	25t, BALL
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
COMMENT	
フェンダー腐食、穴多数あり FENDERS: CORRODED & MUCH HUGE HOLES	
OUTRIGGERS	
OUTRIGGERS	<input checked="" type="radio"/> X · H
OUTRIGGERS COND.	<input type="radio"/> FAIR · Attn
COMMENT	
エア一漏れ大 MUCH AIR LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。