

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/10/4	MAKE	CAT	MODEL	320GC-07A
SERIAL	CAT00320HKTN00412		STAMP	CAT00320HKTN00412	
HR METER	4997	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b> C4.4 <b>S/N</b>	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
<b>MAIN PUMP</b>	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
<b>COOLING SYSTEM</b>	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
<b>OPERATING SYSTEM</b>	
Swing	FAIR · Attn
Travel	FAIR · Attn
<b>INTERIOR See Photos. 写真参照</b>	
Operator's Seat	FAIR · Attn
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
<b>BOOM / ARM / BKT</b>	
Boom	FAIR · Attn
Boom Cylinder	FAIR · Attn
Arm	FAIR · Attn
Arm Cylinder	FAIR · Attn
BKT	FAIR · Attn ピンガタあり PIN: LOOSE
BKT Cylinder	FAIR · Attn

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b> 両側ピンブッシュ割れあり PIN BUSHES: BROKEN	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
<b>COMMENT</b> ボディヘコミ多数あり BODY: A LITTLE DEFORMED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。