

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/10/3	MAKE	TADANO	MODEL	TR-160M-2
SERIAL No.	PLATE : 525236	STAMP :		TR161-0111	
HR METER	2074	HR	Odometer	9462	km
TIRE SIZE	12.00R24	YEAR		YR	

ENGINE : MODEL		S/N	
Oil leakage	FAIR • Attn		
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	FAIR • Attn		
Oil	FAIR • Attn		
Exhaust Color	FAIR • Attn		
OPERATION PUMP			
Sound	FAIR • Attn		
Oil leakage	FAIR • Attn		
Power	FAIR • Attn		
COOLING SYSTEM			
Radiator	FAIR • Attn		
Oil Cooler	FAIR • Attn		
OPERATING SYSTEM			
Computer	OK • NG		
Swing	FAIR • Attn		
Travel	FAIR • Attn		
TRANSMISSION			
Transmission	FAIR • Attn		
No. OF GEARS	3	GEARS	
No. of DRIVE WHEELS	4	WD	
INTERIOR See Photos. 写真参照			
Operator's Seat	FAIR • Attn		
Inside Cover	FAIR • Attn		
Glasses	FAIR • Attn		
AirCon	A/C	H/C • H only • C only • None	
COMMENT			

BOOM		
No. of Section	4	SECTIONS
CRACK/ENFORCEMENT	<input type="radio"/> FAIR ▪ Attn	
DERRICKING CYL.	<input type="radio"/> FAIR ▪ Attn	
EXTENSION CYL.	<input type="radio"/> FAIR ▪ Attn	
JIB	YES ▪ <input checked="" type="radio"/> NO	
JIB TYPE	STD ▪ PWR	
MAIN & SUB WIRE	<input checked="" type="radio"/> YES ▪ NO	
HOOK	16t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
COMMENT		
OUTRIGGERS		
OUTRIGGERS	<input checked="" type="radio"/> X ▪ H	
OUTRIGGERS COND.	<input type="radio"/> FAIR ▪ Attn	
COMMENT		
旋回ロックピン下りない SWING LOCK PIN: UNABLE TO LOCK		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。