

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/10/3	MAKE	TADANO	MODEL	TR-200M-4
SERIAL No.	PLATE :	521457	STAMP :	TR202-0303	
HR METER	4037	HR	Odometer	2368	km
TIRE SIZE	14.00R24	YEAR	YR		

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR <input checked="" type="radio"/> Attn *1	
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	
<b>OPERATION PUMP</b>		
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	
Power	FAIR <input checked="" type="radio"/> Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR <input checked="" type="radio"/> Attn	オイル混入あり OIL: MIXED
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	
<b>OPERATING SYSTEM</b>		
Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input checked="" type="radio"/> Attn	
Travel	FAIR <input checked="" type="radio"/> Attn	
<b>TRANSMISSION</b>		
Transmission	FAIR <input checked="" type="radio"/> Attn	
No. OF GEARS	3	GEARS
No. of DRIVE WHEELS	4	WD
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	
Inside Cover	FAIR <input checked="" type="radio"/> Attn	
Glasses	FAIR <input checked="" type="radio"/> Attn	
AirCon	A/C <input checked="" type="radio"/> H/C <input checked="" type="radio"/> · H only · C only · None	
<b>COMMENT</b>		

<b>BOOM</b>	
No. of Section	4 SECTIONS
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn 油漏れあり OIL LEAKING
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn
JIB	YES <input type="radio"/> NO <input checked="" type="radio"/>
JIB TYPE	STD <input type="radio"/> PWR
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO
HOOK	20t, BALL
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
<b>OUTRIGGERS</b>	
OUTRIGGERS	X <input checked="" type="radio"/> H
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn
<b>COMMENT</b>	
*1 E/Gヘッド油漏れあり CYLINDER HEAD: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。